

property from the east is improved enough to meet fire apparatus standards (attached). 2. The turnaround area is as illustrated in the

2 images attached.

